File No.TTD-34022(31)/191/2024-PROCURMENT SEC-TTD



e-Procurement Tender Notice (TTD Web site & Notice Board) MARKETING DEPARTMENT, T.T.Devasthanams, Tirupati. Roc.No. TTD-34022(31)/191/2024 Dated: -09-2024

e-Tenders are invited for "procurement of 25,00,000 Nos of Paper plates(with								
silver	foil)	from	the	"Manufacturers"	by	the	Marketing	Department,
T.T.Devasthanams, Tirupati for a period of two months. The EMD of Rs.90,000/-								
(Rupees Ninety thousand only) is to be remitted through ONLINE in favour of the								
Executive Officer, TTD, Tirupati payable at Tirupati.								

Date of start of Downloading- 13-09-2024End date of downloading- 19-09-2024 at 1.00 PM

(Last date for submission)

Date of opening of tender

Tech.Bid	- 19-09-2024 at 3-30 PM
Fin. Bid	- 19-09-2024 at 4-30 PM

Period of procurement - As per schedule

Tender documents can be downloaded from the website: <u>http://tender.eprocurement.gov.in</u>.

For further details contact phone numbers: 0877-2264079, 2264555. FAX : 0877-2264554.

**GENERAL MANAGER (P)** 

## File No.TTD-34022(31)/191/2024-PROCURMENT SEC-TTD

## **Specifications**

S. No.	Name of the item	Description					
1	Paper plates	a) 20 cms top dia (± 0.5 cms)					
	(with silver foil)	b) 15 cms inner dia ( <u>+</u> 0.5 cms)					
		c) 2.5 cms (minimum) height with Bowl shape.					
		d) Weight: 17 ± 01 grams					
		e) Inside of the plate with Silver Foil (food grade) and overall					
		migration as per IS 9845 – 1988 & IS 10146 - 1982.					
		f) Bowl shape and bottom of the Plate should be strong					
		enough to withstand minimum 500 grams without					
		deformation.					
		g) Marking as "TTD" on the bottom of the paper plate, ink					
		should not get migrated to other plates and shall be legible					
		when contacted with water.					
		h) Plate must be of corrugated 3 ply.					
		i) GSM should be not less than 375.					
•	The plates without bowl shape will be summarily rejected.						
•	• The supply must be made in "CORRUGATED BOXES (Carton Boxes) of not LESS						
	THAN 5 PLY" to sustain the transportation without causing buckling of paper plates.						